

ECS Configuration Change Request

Page 1 of 1 Page(s)

1. Originator Brad Koenig	2. Log Date: 2/17/00	3. CCR #: 00-0170	4. Rev: -	5. Tel: 301-925-1145	6. Rm #: 2072F	7. Org. DADS
8. Title of Change: Add Stand Alone D3 Tape Drive to Functionality Lab.						
9. Originator Signature/Date <i>Bradley Koenig</i> 2-17-00		10. Class IN	11. Type: CCR	12. Need Date: 02/25/2000		
13. Office Manager Signature/Date <i>Ala. S. Lee</i> 2/17/00		14. Category of Change: Update Baseline		15. Priority: (If "Emergency" fill in Block 28). Routine		
16. Documentation/Drawings Impacted:		17. Schedule Impact:		18. CI(s) Affected: DIS DRP		
19. Release Affected: 5B, 6A		20. Date due to Customer:		21. Impl. Date:		22. Estimated Cost: None
23. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
24. Description of Change: (use additional Sheets if necessary) Add Kidnaped and Sioux to the current D3 stand alone tape drive configuration. The Functionality Lab needs access to a D3 tape drive to develop and test an automated EDOS backup ingest solution and to perform Aster ingest checkout.						
25. Proposed Solution: (use additional sheets if necessary) Replace the existing 4x2 scsi switch with a 4x6 scsi switch. The 4x6 switch adds two additional host and device ports, the new host ports enable Kidnaped and Sioux to share the D3 tape drives. A 4x6 scsi switch (EIN 3692) is available to accomplish this change. See attached scsi switch drawings for current and new configurations.						
26. Alternate Solution: (use additional sheets if necessary) Remove a D3 drive from STK Wolfcreek and install into STK stand alone rack. This solution would require the purchase of a D3 mounting kit from STK and the addition of another scsi switch.						
27. Consequences if Change(s) are not approved: (use additional sheets if necessary) Integration testing for 6A EDOS Backup/Restore will not be able to be performed in the functionality lab.						
28. Justification for Emergency (if Block 15 is "Emergency"):						
29. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> Mini-DAAC <input checked="" type="checkbox"/> VATC <input type="checkbox"/> EDC <input type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input checked="" type="checkbox"/> Other PVC, Functionality Lab						
30. Board Comments:				31. Work Assigned To:		
32. EDF/REL2 CCB Chair (Sign/Date): <i>David A. Burt</i> 2/21/00		33. Disposition: <u>Approved</u> A/C Fwd/ECS Fwd/ESDIS		34. (TBD)		
35. M&O CCB Chair (Sign/Date):		36. Disposition: Approved A/C Fwd/ECS Fwd/ESDIS		37. CM Manager's Closure:		
38. ECS CCB Chair (Sign/Date):		39. Disposition: Approved A/C Disapproved		40. CCR Closed Date:		